

Supplementary Fig. 2 Quality check of breath samples. PCA of breath samples and blanks. Projected data points in different types of samples are shown by different colors. PC1 explains ~24% and PC2 ~14% of variance and show separation of breath from blanks. PCA, principal component analysis.